



Survey Bergse Plassen, Rotterdam

The Bergse Plassen consist of two lakes of 680,000 and 430,000 m² with several islands. Most of the bank revetments are private property. In the past decades several suburbs of Rotterdam discharged their waste water in the Bergse Plassen, contaminating the bed material. The Hoogheemraadschap of Schieland (a regional waterboard) has dredged the Bergse Plassen.

Svašek Hydraulics has surveyed the post dredged technical condition of all the bank revetments in the Bergse Plassen. These technical conditions were recorded by photograph and described by the surveyor. Obstacles and cables were located by GPS and recorded. Finally water depth and silt thickness measurements were carried out.

Client

Hoogheemraadschap van Schieland, The Netherlands

Location

Bergse Plassen, Rotterdam, the Netherlands

Date

2000

Services

surveying and reporting the post dredged situation of all the bank revetments in the Bergse Plassen, locating obstacles and cables with DGPS, water depth and silt thickness measurements

Svašek Hydraulics

Schiehaven 13G, P.O. Box 91, 3000 AB Rotterdam, The Netherlands.

Phone +31 10 467 13 61, Fax +31 10 467 45 59, Internet: www.svasek.com, E-mail: info@svasek.com

SV1201